NOVEMBER 6, 2007

MICHAEL W. DOBBINS
CLERK, U.S. DISTRICT COURT

07 C 6294



JUDGE MORAN MAGISTRATE JUDGE COX



General:

The quality of the printing and molding is poor compared to the norm. The molded parts have a lot of flash and less detail.

LEFT COLUMN = KNOWN LEGITIMATE DEVICE.


RIGHT COLUMN = SUSPECT COUNTERFIT DEVICE.

Page 1 – Device #4	
No Photo of known good carton.	Source So
	The coil voltage and voltage code have been changed via small stickers. Date Code and Country of Origin are missing.




Schneider Electric North American Operating Division 8001 Hwy. 64 East Knightdale, NC 27545-9023 Tel 919-266-3671 Fax 919-266-4460 www.SquareD.com







Schneider Electric








Schneider Electric







Schneider Electric

